CLASSIFICATION DECET/CONTROL OFFICIALS ONLY CENTRAL INTELLIGENCE AGENCY REPORT NO. INFORMATION REPORT 25X1A CD NO. COUNTRY Germany (Russian Zone) DATE DISTR. 1949 1 Nov. SUBJECT Washing of Uranium Ore in NO. OF PAGES Oberschlema 25X1A 21-18-4 mil NO. OF ENCLS. PLACE **ACQUIRED** 25X1A DATE OF IN SUPPLEMENT TO REPORT NO. 25X1X Location: The OBEESCHLEMA (N 51/K 43) Ore Washing Flant, Object 99, was in the former Blaufarben Plant. 25X1X 2. Work schedule : The ore passed through crushers to the ball mill. It then entered a jig (or centrifugal') sieve and was mixed with water. It was then sent through the pipe line into the "Stromapparat" (power apparatus) and then on vibrator grates called "Herde". 3. There were 20 vibrator grates in the fall of 1948 and 80 vibrator grates in February 1949. According to information from a female worker still employed in the plant after rebruary 1949 there were 101 vibrator grates in June 1949. 4. After being sifted by the grates the uranium ore was put into canisters and sent to the laboratory for testing. It finally went to drying kilns. 25X1X b. The ore was graded in the laboratory as follows: A 1 (black color) A 2 (somewhat lighter than A 1) B 1 (dark brown) B 2 (brown) G 1 (linht brown) C 2 (yellowish) 6. Manager: PROSTEROV (Soviet) 7. Work force: first shift: German manager Emil WOLF second shift: German manager FUCHS third shift: Ger san manager GARONZI The total work force numbered 350 to 400 Germans and about 25X1X 100 Seviets. 8. Emil WOLF once remarked that three grams of pure uranium were produced in the OBERSCHLEMA Ore Washing Plant in 1948. CLASSIFICATION SEC DISTRIBUTION NSRB NAVY Desument No No Change in Class. Teclassified

Approved For Release 2001/03/17 : CIA-RDP82-00457R003600430008-1

Class, Changed To: TS S &

Auth.: HR 19-2